

- 1. Cross-domain clock synchronization applies as required but is not highlighted.
- 2. Ensure that TUxyTMR counter is reset to zero by setting CLR command.
- 3. The RUN trace illustrates the internal Timer Clock domain run/stop signal. Clock sync delays apply before the value appears in the RUN SFR bit.
- 4. The uncertainty of the output is due to the prescaler setting. 5. Timer Out (Level) rises along with ERS when START = Rising/Either ERS Edge.
- 6. Cleared by software.