1: Latency due to reference wakeup (low-power mode to full-power mode) and regulator up voltage scaling.
2: Latency due to VDDCORE_RAM_PD switching ON.
3: Latency due to clock source wakeup time.
4: Latency due to NVM wakeup time from deep power down mode.