

Not secure 192.168.0.58/index.htm Finish update

# MICROCHIP

## PD-IES008-DC240W

Port 2

**QoS Egress Port Scheduler and Shapers Port 2**

Scheduler Mode: Strict Priority

**Queue Shaper**

Enable	Rate	Unit	Rate-type	Excess	Credit
<input type="checkbox"/>	500	kbps	Line	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	500	kbps	Line	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	500	kbps	Line	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	500	kbps	Line	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	500	kbps	Line	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	500	kbps	Line	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	500	kbps	Line	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	500	kbps	Line	<input type="checkbox"/>	<input type="checkbox"/>

**Queue Scheduler**

Cut-through
<input type="checkbox"/>

**Port Shaper**

Enable	Rate	Unit	Rate-type
<input type="checkbox"/>	500	kbps	Line

**Diagram:** The configuration shows a strict priority scheduler. Seven queues (Q1-Q7) are connected to a central vertical oval labeled "STRICT". From the bottom of this oval, a single line leads to a port shaper with a rate of 500 kbps.

Save Reset Back