

Notes: 1. SS_out is not shown.

2. Software must wait for shift-register empty (SRMTIF) before changing TXR, RXR, SPIXTCNT and SPIXTWIDTH controls. In this case, this is not considered an imposition because the client likely needs time to load output data.