

PIT64B_MR.CONT=0

Write PIT64B_MR,

Period = P1 (MSB part)

Period = P2 (MSB part)

Period = P3 (MSB part)

PIT64B_MSBPR

Write PIT64B_LSBPR

Period = P3 (LSB part)
and start trigger

Write PIT64B_CR.START=1

start commands
= no effect

start command
= no effect

64-bit timer value

Period = P1

Period = P2

Period = P3

Start
Period = P3

Start
Period = P2

Start
Period = P3

PIT64B_ISR.PERIOD

Read PIT64B_ISR

