

PIT64B\_MR.CONT=0

Write PIT64B\_MR,  
PIT64B\_LSBPR,  
PIT64B\_MSBPR

Period = P1

Period = P2

No effect start commands

Write PIT64B\_CR.START=1

Period = P1

Period = P2

64-bit timer value

PIT64B\_ISR.PERIOD

Read PIT64B\_ISR

PIT64B\_ISR.OVRE

