


Isolated DC Power
Supply (J3)



PIC32CXMTSH

SWD 10-pin 50mils



No Metrology
Sensors Connected
(J1, J2, J10 and J11)

PIC32CXMTSH-DB Board



20 to 10-pin
Adapter



J-Link SWD
Debugger



PC