

Baud Rate
Clock

RXD

Start
Bit

D0

D1

D2

D3

D4

D5

D6

D7

Bad
Parity
Bit

Stop
Bit

Write
US_CR

RSTSTA = 1

PARE

Parity Error
Detect
Time

Flags
Report
Time

RXRDY

