


Case 1: PWM Pulse Truncated Immediately



Case 2: PWM Pulse Truncated after 'Greater than' Compare is True

