


Brush DC Forward Mode – OUTM[2:0] = 101



Brush DC Reverse Mode – OUTM[2:0] = 100

