


Case 1: PWM Pulse Truncated Immediately



Case 2: PWM Pulse Truncated after Greater than Compare is True

