



Bit 0 – SETTLED Op Amp has Settled

This bit is cleared when the op amp is waiting for settling time related to enabling or configuration changes.

This bit is set when the allowed settling time is finished.