

- 1 Fuse read in. Pull-up enabled. Ready to receive init.
- 2 Drive low from debugger to request UPDI clock.
- 3 UPDI clock ready; Communication channel ready.

