

PIT64B_MR.CONT=1

Write PIT64B_MR,
PIT64B_LSBPR,
PIT64B_MSBPR

Period = P1

Period = P2 = no effect

Write PIT64B_CR.START=1

Period = P1

No effect start commands

64-bit timer value

PIT64B_ISR.PERIOD

Read PIT64B_ISR

PIT64B_ISR.OVRE

