



CAUTION

Communication Failure.

Do not connect the hardware before installing the software and USB drivers.



CAUTION

Debugger or Target Damage.

Do not change hardware connections while the debugger or target is powered.