

```
C:\Microsemi\Tools>nfkminfo -k seeinteg userdata-signer | find "hash"
```

```
hash          e0d5146a74ec125f22d4b15088d424b963b88109
```