Bit	7	6	5	4	3	2	1	0
[RUNSTDBY					PRESC[2:0]		ENABLE
Access	R/W				R/W	R/W	R/W	R/W
Reset	0				0	0	0	0