

Generate Content Manager ?

Project Resources

MCC v5.7.0

Drivers

Timer

TCB0

UART

UART0

System

CLKCTRL

Configuration Bits

Interrupt Manager

Main

Pins

Toolbar ?

Easy View

Configuration Settings

Custom Name

UART0

Requested Baudrate

115200

Calculated Baudrate

115273

Baud Rate Error (%)

0.063

Parity

None

Data Size

8

Stop Bits

1

Flow Control Mode

None

Redirect Printf to UART

Ensure Redirect to Printf is enabled for only one UART driver.



Interrupt Settings

Interrupt Driven



Dependency Selector

UART PLIB Selector

USART0