

$$R136 = R134 * 0.6V / (12V - 0.6V) = 526$$

