


Target Mode



Process All the Outstanding Responses and Received data

Issue Master Request (MR)

Set
I3CxCNTRLEXT[REQACKCTRL]
= 0 to accept GETACCMST CCC

I3CxINTSTA
[BUSOWNSTA]
= 1?

Process All the Outstanding Responses and Received data
(if applicable)

Flush All FIFOs and Queues

Program DAT with the associated
target details

Write I3CxCNTRL[RESUME] = 1

Controller Mode