

Note: If I/O management is configured in Privileged-Access mode, PIO_P_* registers are acting, whereas the others have no effect

