


Direction Change under normal conditions



No direction change due to particulate contamination masking a reflective bar

